




Lineární sety  
serie ALGS-OP



Označení	Rozměry (mm)											Únosnost (N)		Hmotnost (kg)
	ød	øD	h	H	A	E2	A1	L1	E1	E3	(°)	C <sub>d</sub>	C <sub>0</sub>	
ALGS-OP-12-KS	12	22	18	28	52	42 <sup>+0,15</sup>	30	20	10	7,7	78	750	600	0,09
ALGS-OP-16-KS	16	26	22	33,5	56	46 <sup>+0,15</sup>	34	22	11	10,1	78	920	730	0,12
ALGS-OP-20-KS	20	32	25	42	70	58 <sup>+0,15</sup>	40	28	14	10,0	60	1560	1300	0,25
ALGS-OP25-KS	25	40	30	51	80	68 <sup>+0,15</sup>	50	40	20	12,5	60	2600	2290	0,49
ALGS-OP30-KS	30	47	35	60	88	76 <sup>+0,2</sup>	58	48	24	13,6	54	3330	2910	0,78
ALGS-OP40-KS	40	62	45	77	108	94 <sup>+0,2</sup>	74	56	28	18,2	54	5720	5100	1,28